

CONSTRUCTION EQUIPMENT
646452 MOSIAC CO VOLVO A45G 352974 - BRAKE COOLING SYST

Sample No: VCP440808 Oil Type: VOLVO WB 102

Job No: 646452 MOSIAC CO

SAMPLE SAMPLE	INFORMATION				
Sample Number		VCP440808			
Sample Date		14 Dec 2023			
Machine Hours		3408			
Oil Hours		3408			
Oil Changed		Not Changd			
Sample Status		ABNORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	40.5			
V13C @ 40 C	CSt				
VOLVO					
CONTAM	IINATION				
Water	%	NEG			
Silicon	ppm	25			
Sodium	ppm	■ 8			
Potassium	ppm	2			
VOLVO	ICTAL C				
WEAR M	IF I ALS				
Iron	ppm	■30			
Copper	ppm	<u> </u>			
Lead	ppm	■<1			
Tin	ppm	■<1			
Aluminum	ppm	1			
Chromium	ppm	1			
Molybdenum	ppm	■<1			
Nickel	ppm	■8			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	2			
Vanadium	ppm	0			
ADDITIV	71				
_	-				
Calcium	ppm	3523			
Magnesium	ppm	7			
Zinc	ppm	1494			
Phosphorus	ppm	1417			
Barium	ppm	■0			
Boron	ppm	108			



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0093 **Unique No:** 10862344 Signed: Don Baldridge Report Date: 07 Feb 2024



CONSTRUCTION EQUIPMENT





GRAPHS

