

Sample No: VCP435620

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No: 462431 WATER FRONT

SAMPLE	E INFORMATIO	N			
Sample Number		VCP435620	VCP426676		
Sample Date		10 Feb 2024	12 Aug 2023		
Machine Hours		7777	7325		
Oil Hours		0	0		
Oil Changed		Not Changd	Changed		
Sample Status		NORMAL	ABNORMAL		
OIL CON	INITION				
	<u> </u>			<u>.</u>	
Visc @ 40°C	cSt	27.4	27.9		
VOLVO					
CONTAN	MINATION				
Water	%	NEG	NEG		
Silicon	ppm	4	1 4		
Sodium	ppm	4	6		
Potassium	ppm	<1	1		
VOLVO	ACTAL C				
WEAR	METAL2				
Iron	ppm	■31	■26		
Copper	ppm	■33	■29		
Lead	ppm	■0	0		
Tin	ppm	5	4		
Aluminum	ppm	16	■18		
Chromium	ppm	■0	0		
Molybdenum	ppm	■ <1	0		
Nickel	ppm	4	4		
Titanium	ppm	0	0		
Silver	ppm	0	0		
Manganese	ppm	1	1		
Vanadium	ppm	0	0		
VOLVO					
ADDITIV	VES				
Calcium	ppm	■82	□80		
Magnesium	ppm	2	3		
Zinc	ppm	6	□0		
Phosphorus	ppm	191	□182		
Barium	ppm	0	0		
Boron	ppm	■ 68	87		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0093Unique No:10875265Signed:Wes DavisReport Date:14 Feb 2024



CONSTRUCTION EQUIPMENT





GRAPHS

