

Sample No: VCP444114
Oil Type: VOLVO WB 101

Job No: X11169 OLD CASTLE

VOLVO	LINEODMATION			
	INFORMATION			_
Sample Number		VCP444114	 	
Sample Date		09 Feb 2024	 	
Machine Hours		1000	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	41.6	 	
VOLVO	4015-21611			
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	22	 	
Sodium	ppm	0	 	
Potassium	ppm	4	 	
WEAR N	AETALC			
	JETAL2			
Iron	ppm	65	 	
Copper	ppm	2	 	
Lead	ppm	1	 	
Tin	ppm		 	
Aluminum	ppm	1	 	
Chromium	ppm	4	 	
Molybdenum	ppm	22	 	
Nickel	ppm	1	 	
Titanium	ppm	<1	 	
Silver	ppm	<1	 	
Manganese	ppm	14	 	
Vanadium	ppm	<1	 	
ADDITIV	JES			
Calcium	ppm	5233	 	
Magnesium	ppm	15	 	
Zinc	ppm	2151	 	
Phosphorus	ppm	1838	 	
Barium	ppm	■0	 	
Boron	ppm	■177	 	
231011	PPIII			



SCOTT EQUIPMENT COMPANY LLC - Texarkana 5401 SANDERSON LANE TEXARKANA, AR US 71854 Contact: JAMES DOSS jdoss@scottcompanies.com T:

т. F:

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO1034Unique No:10883384Signed:Don BaldridgeReport Date:17 Feb 2024



CONSTRUCTION EQUIPMENT





