

CONSTRUCTION EQUIPMENT

4001 SYNERGY VOLVO ECR235 314207 - REAR RIGHT FINAL DRI

Sample No: VCP455370
Oil Type: {unknown}
Job No: 4001 SYNERGY

VOLVO	- INFORMATIO			
SAMPLE	E INFORMATIO	N		
Sample Number		VCP455370	 	
Sample Date		09 Feb 2024	 	
Machine Hours		4205	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	186	 	
		_		
VOLVO	AINT TION			
_	MINATION			
Water	%	NEG	 	
Silicon	ppm	<u> </u>	 	
Sodium	ppm	■0	 	
Potassium	ppm	■8	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	2	 	
Lead	ppm	<1	 	
Tin	ppm	O	 	
Aluminum	ppm	4	 	
Chromium	ppm	<u></u> 30	 	
Molybdenum	ppm	5	 	
Nickel	ppm	3	 	
Titanium	ppm	1	 	
Silver	ppm	<1	 	
Manganese	ppm	13	 	
Vanadium	ppm	<1	 	
	P P			
VOLVO	IFC		 	
ADDITIV	E2			
Calcium	ppm	61	 	
Magnesium	ppm	2	 	
Zinc	ppm	30	 	
Phosphorus	ppm	311	 	
Barium	ppm	0	 	
Boron	ppm	2	 	



ALTA EQUIPMENT COMPANY

5210 REESE ROAD DAVIE, FL US 33314 Contact: N. FACEY nfacey@altaequipfl.com T: (954)581-4744 F: (954)583-0318

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental level of silicon (Si) above normal indicating ingress of seal material. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0095Unique No:10883392Signed:Don BaldridgeReport Date:17 Feb 2024



CONSTRUCTION EQUIPMENT





