

CONSTRUCTION EQUIPMENT
SWO-069745 APAC AL VOLVO L150H 6816 - DIESEL ENGINE

Sample No: VCP443300

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: SWO-069745 APAC AL

SAMPLE IN	IFORMATION				
Sample Number		VCP443300	VCP289488	VCP271671	
Sample Date		15 Feb 2024	07 Oct 2020	28 May 2020	
Machine Hours		7536	2531	2006	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	ABNORMAL	ABNORMAL	
OIT CONDI	TION				
Visc @ 100°C	cSt	■13.5	13.0	12.6	
Base Number (BN)	mg KOH/g	6.8			
Oxidation (PA)	%	53	53	53	
CONTAMIN	IATION				
Water	%	NEG	NEG	NEG	
C + 0/	0/		-0.1	-04	

CONTAMINATION						
Water	%	NEG	NEG	NEG		
Soot %	%	■ 0.1	■ 0.1	□ 0.1		
Nitration (PA)	%	58	69	70		
Sulfation (PA)	%	54	55	55		
Glycol	%	NEG	NEG	NEG		
Fuel	%	<1.0	<1.0	<1.0		
Silicon	ppm	■8	5	5		
Sodium	ppm	■<1	3	■ 3		
Potassium	ppm	■ 0	5	3		

VOLVO WEAD META					
WEAR META	17				
	opm	■ 5	□ 6	1 5	
_	opm	■ <1	1 27	<u>122</u>	
	ppm	■<1	2	- <1	
Tin p	opm	-<1	0	- <1	
Aluminum p	opm	■3	1	- <1	
Chromium p	opm	■0	< 1	 <1	
Molybdenum p	opm	79	■ 3	4	
Nickel	opm	■0	< 1	<1	
Titanium p	opm	0	<1	0	
Silver	opm	■ 0	0	0	
Manganese p	opm	0	<1	<1	
Vanadium p	opm	0	0	0	

ADDITIVES					
ppm	1568	■1523	1240		
ppm	241	■834	612		
ppm	1162	■851	7 02		
ppm	■974	719	649		
ppm	0	□0	0		
ppm	246	5 2	5 9		
	ppm ppm ppm ppm ppm	ppm	ppm	ppm	



COWIN EQUIPMENT COMPANY

2238 PINSON VALLEY PARKWAY BIRMINGHAM, AL US 35217

Contact: BRANTLY CLAY bclay@cowin.com

T:

F: (205)856-2106

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VOLVO8528 **Unique No:** 10886747 Signed: Wes Davis Report Date: 21 Feb 2024



CONSTRUCTION EQUIPMENT





