CONSTRUCTION EQUIPMENT SPM674735-10 VOLVO EC950FL 410112 - LEFT SWING DRIVE

 Sample No:
 VCP436143

 Oil Type:
 {unknown}

 Job No:
 SPM674735-10

VOLVO

SAMPL	E INFORMATION			
Sample Number		VCP436143	 	 •
Sample Date		17 Feb 2024	 	 ALTA EQUIPMENT COMPANY
Machine Hours		1239	 	 5151 DR MARTIN LUTHER KING BLVD
Oil Hours		0	 	 FORT MYERS, FL
Oil Changed		N/A	 	 US 33905
Sample Status		ABNORMAL	 	 Contact: TODD LARK
				tlark@altaequipfl.com
VOLVO	NDITION			T:
			 	 F: (239)481-3302
Visc @ 40°C	cSt	156	 	
VOLVO				Diagnosis
CONTA	MINATION			
Water	%	NEG	 	 No corrective action is recommended at this time. Resample at the next
Silicon	ppm	16	 	 service interval to monitor. Please
Sodium	ppm	3	 	 specify the brand, type, and viscosity
Potassium	ppm	0	 	 of the oil on your next sample.Gear
1 otdssidim	ppiii			wear is indicated. There is no
VOLVO				indication of any contamination in
WEAR	METALS			the oil. The condition of the oil is
Iron	ppm	423	 	 acceptable for the time in service.
Copper	ppm	72	 	
Lead	ppm	0	 	
Tin	ppm	 <1	 	
Aluminum	ppm	2	 	
Chromium	ppm	5	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	7	 	
Vanadium	ppm	0	 	
ADDITI	VES			
Calcium	ppm	83	 	 •
Magnesium	ppm	0	 	
Zinc	ppm	110	 	
Phosphorus	ppm	302	 	
Barium	ppm	0	 	
Boron	ppm	3	 	
501011	PPIII			

 Depot:
 VOLVO090

 Unique No:
 10888022

 Signed:
 Sean Felton

 Report Date:
 22 Feb 2024

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

