

## CONSTRUCTION EQUIPMENT 74852 LAKE CONWAY TAKEUCHI TB225 122600181 - REAR LEFT



Sample No: VCP445673 Oil Type: {unknown}

Job No: 74852 LAKE CONWAY

VOLVO	INCODMATIO	7		
	INFORMATIO	<u> </u>		
Sample Number		VCP445673	 	
Sample Date		19 Feb 2024	 	
Machine Hours		811	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIT CON	NITION			
			 <u> </u>	
Visc @ 40°C	cSt	<b>230</b>	 	
VOLVO				
CONTAM	IINATION			
Water	%	NEG	 	
Silicon		MEG ■ 6	 	
Sodium	ppm	_	 	
	ppm	<b>1</b>		
Potassium	ppm	■1	 	
VOLVO				
WEAR M	IETALS			
Iron	ppm	<b>81</b>	 	
Copper	ppm	<b>□</b> <1	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>0</b>	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	8	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese		1	 	
Vanadium	ppm	0	 	
variaululli	ppm	U	 	
VOLVO				
ADDITIV	ES			
Calcium	ppm	535	 	
Magnesium	ppm	38	 	
Zinc	ppm	222	 	
Phosphorus	ppm	889	 	
Barium	ppm	3	 	
Boron	ppm	145	 	
201011	PPIII	173		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093 **Unique No:** 10896982 Signed: Don Baldridge Report Date: 26 Feb 2024



## **CONSTRUCTION EQUIPMENT**





## **GRAPHS**

