CONSTRUCTION EQUIPMENT SW-30086-1 RANGO VOLVO R100E 121020 - LEFT BRAKE

Sample No: VCP422761 Oil Type: {unknown} Job No: SW-30086-1 RANGO

VOLVO

VOLVO				
SAMPLE	INFORMATION	l		
Sample Number		VCP422761	 	
Sample Date		20 Feb 2024	 	 ARNOLD MACHINERY COMPAN
Machine Hours		4057	 	 2975 WEST 2100 SOUTH
Oil Hours		0	 	 SALT LAKE CITY, UT
Oil Changed		Not Changd	 	 US 84119
Sample Status		ABNORMAL	 	 Contact: TJ LARK
				tlark@arnoldmachinery.com
OIL CON				T: (801)972-4000
				 F: (801)975-9434
Visc @ 40°C	cSt	44.7	 	
VOLVO				Diagnosis
CONTAN	AINATION			-
Water	%	NEG	 	 No corrective action is recommer at this time. We recommend an e
Silicon	ppm	43	 	 resample to monitor this
Sodium	ppm	1	 	 condition.The copper level is
Potassium	ppm	0	 	 abnormal. All other component v
	ppm			rates are normal. There is no
VOLVO				indication of any contamination i
🤍 WEAR M	NETALS			the fluid. The condition of the flu
ron	ppm	12	 	 acceptable for the time in service
Copper	ppm	A 358	 	
ead	ppm	 <1	 	
Tin	ppm	 <1	 	
Aluminum	ppm	4	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Vickel	ppm	9	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
	/ES		 	
Calcium	ppm	1893	 	
Magnesium	ppm	8	 	
Zinc	ppm	647	 	
Phosphorus	ppm	659	 	
Barium	ppm	0	 	
Boron	ppm	0	 	
001011	ppm	Ū.		

ded arly ear d is

Depot: VOLVO8770 Unique No: 10900269 Signed: Jonathan Hester Report Date: 29 Feb 2024


Contact/Location: TJ LARK - VOLVO8770

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO8770 [WUSCAR] 06102039 (Generated: 02/29/2024 14:55:18) Rev: 1

Contact/Location: TJ LARK - VOLVO8770