

## CONSTRUCTION EQUIPMENT VOLVO A25G 740348 - REAR AXLE



Sample No: VCP440060

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No:

INFORMATION				
		VCP0007703	VCP336947	
			3	
	ATTENTION	NONIVIAL	NONWAL	
DITION				
cSt	<b>269</b>	□299	<b>289</b>	
MATION				
ppm	_	_	_	
ppm	_		_	
ppm	■0	<b></b> <1	<1	
TETALS				
	<b>□</b> 15 <i>4</i>	m 15/	<b>□</b> 302	
		_		
	_		_	
			_	
	_		_	
		_		
			_	
	_			
			_	
ppiii	<b>\</b> 1	U	\	
EZ				
ppm	<b>153</b>	<b>58</b>	■86	
ppm	<u> </u>	<b>1</b> 3	<u>20</u>	
ppm	■95	□56	□ 58	
ppm	<b>941</b>	992	□981	
			0	
ppm	<b>138</b>	179	■156	
	DITION  cSt  IINATION  %  ppm  ppm  ppm  ppm  ppm  ppm  ppm		VCP440060         VCP0007703           09 Feb 2024         05 May 2023           11358         0           0         0           N/A         N/A           ATTENTION         NORMAL    DITION  cSt  DITION  cSt  Popm  St  Popm  Popm  St  Popm  P	VCP440060   VCP0007703   VCP336947   O9 Feb 2024   05 May 2023   09 Nov 2021   11358   0   8776   O   1500   N/A   N/A   Changed   NORMAL   NORMA



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. Additive levels indicate the addition of a different brand, or type of oil. Confirm oil type.

Depot:VOLVO0093Unique No:10900827Signed:Don BaldridgeReport Date:29 Feb 2024

Submitted By: TECHNICIAN ACCOUNT



## **CONSTRUCTION EQUIPMENT**





