

## CONSTRUCTION EQUIPMENT BLAIR VOLVO A30G 60110 - TRANSMISSION (AUTO)



Sample No: VCP449074
Oil Type: {unknown}
Job No: BLAIR

VOLVO				
SAMPLE	INFORMATION			
Sample Number	<del>-</del>	VCP449074	 	
Sample Date		15 Mar 2024	 	
Machine Hours		16101	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CONE	DITION			
Visc @ 40°C	cSt	<b>29.0</b>	 	
VOLVO				
CONTAM	INATION			
Water	%	NEG	 	
Silicon	ppm	<b>10</b>	 	
Sodium	ppm	■3	 	
Potassium	ppm	<b>■</b> 0	 	
WEAR M	ETALS			
Iron	ppm	<b>82</b>	 	
Copper	ppm	<u>^</u> 265	 	
Lead	ppm	<b>14</b>	 	
Tin	ppm	<u>^</u> 28	 	
Aluminum	ppm	<b>13</b>	 	
Chromium	ppm	<b>■</b> 0	 	
Molybdenum	ppm	1	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	418	 	
Magnesium	ppm	11	 	
Zinc	ppm	140	 	
Phosphorus	ppm	242	 	
Barium	ppm	0	 	
Boron		47	 	
DOTOTI	ppm	71	 -3-	



HIGHWAY EQUIPMENT AND SUPPLY CO 200 BURKHOLDER DR. EPHRATA, PA US 17522 Contact: CHAD HERRON chad@hwyequip.com T: (717)859-3132 F: (717)859-2698

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:INSEPHUnique No:10930058Signed:Don BaldridgeReport Date:20 Mar 2024



## **CONSTRUCTION EQUIPMENT**





