

CONSTRUCTION EQUIPMENT

SW1030715-2 VOLVO EC480E 315096 - RIGHT SWING DRIVE

Sample No: VCP422757

Oil Type: {unknown}

Job No: SW1030715-2

SAMPLE	INFORMATION			
Sample Number		VCP422757	 	
Sample Date		14 Mar 2024	 	
Machine Hours		904	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
Sample Status		NORWAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	168	 	
VOLVO	AIN A TION			
LUNTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	■20	 	
Sodium	ppm	■<1	 	
Potassium	ppm	■0	 	
VOLVO	AFTALC			
WEAR M	AETAL2			
Iron	ppm	■83	 	
Copper	ppm	62	 	
Lead	ppm	0	 	
Tin	ppm	■0	 	
Aluminum	ppm	2	 	
Chromium	ppm	1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
ADDITIV	IFS			
Calcium	ppm	5	 	
Magnesium	ppm	<1	 	
Zinc	ppm	68	 	
Phosphorus	ppm	321	 	
Barium	ppm	4	 	
Boron	ppm	0	 	



ARNOLD MACHINERY COMPANY 2975 WEST 2100 SOUTH SALT LAKE CITY, UT

US 84119 Contact: TONY PAYAN tpayan@arnoldmachinery.com

T: (801)972-4000 F: (801)975-9434

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8770Unique No:10939399Signed:Don BaldridgeReport Date:25 Mar 2024



CONSTRUCTION EQUIPMENT





