CONSTRUCTION EQUIPMENT AMERICAN IMPORT AUTO VOLVO L 120H 632767 - REAR AXLE

Sample No: VCP437922 **Oil Type:** VOLVO WB 102

TOTATO

Job No:

AMERICAN IMPORT AUTO

Sample Number	-	VCP437922	VCP418272	
Sample Date		14 Mar 2024	03 Aug 2023	
Machine Hours		0	4536	
Oil Hours		0	3000	
Oil Changed		Not Changd	Changed	
Sample Status		NORMAL	NORMAL	
OIL CON	אטדוט			
			<u></u>	 <u>.</u>
Visc @ 40°C	cSt	43.9	41.9	
VOLVO				
CONTAM	INATION			
Water	%	NEG	NEG	
Silicon	ppm	2	15	
Sodium	ppm	□ <1	2	
Potassium	ppm	0	1	
	ppiii			
VOLVO				
VEAR M	ETALS			
Iron	ppm	48	95	
Copper	ppm	0	 <1	
Lead	ppm	0	0	
Tin	ppm	0	0	
Aluminum	ppm	0	1	
Chromium	ppm	 <1	2	
Molybdenum	ppm	0	1	
Nickel	ppm	0	<1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	1	3	
Vanadium	ppm	0	0	

ADDITIVES								
Calcium	ppm	330	4323					
Magnesium	ppm	5	12					
Zinc	ppm	482	1749					
Phosphorus	ppm	383	1388					
Barium	ppm	0	0					
Boron	ppm	11	156					



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Confirm oil type. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093 Unique No: 10940890 Signed: Don Baldridge Report Date: 26 Mar 2024


Contact/Location: KENNY HANEY - VOLVO0093

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06126739 (Generated: 03/26/2024 17:15:58) Rev: 1

Contact/Location: KENNY HANEY - VOLVO0093