

CONSTRUCTION EQUIPMENT
SWO-070729 EPIROC D60-10 TMG23SED0506 - REAR RIGHT FINAL

Sample No: VCP436288 Oil Type: {unknown} Job No: SWO-070729

VOLVO	INFORMATIO	1		
	INFURMATIU			
Sample Number		VCP436288	VCP449245	 
Sample Date		01 Apr 2024	27 Dec 2023	 
Machine Hours		558	263	 
Oil Hours		0	0	 
Oil Changed		Not Changd	Not Changd	 
Sample Status		NORMAL	NORMAL	 
OIL CON	NITION			
Visc @ 40°C	cSt	<b>205</b>	205	 
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	 
Silicon		MEG ■34	15	 
Sodium	ppm	3	<b>1</b> 0	 
Potassium	ppm	3	0	 
Potassium	ppm	3	U	 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>111</b>	<b>□</b> 55	 
Copper	ppm	<b>4</b>	0	 
Lead	ppm	10	<u> </u>	 
Tin	ppm	<b>■&lt;1</b>	0	 
Aluminum	ppm	<b>6</b>	<u> </u>	 
Chromium	ppm	_ 2	1	 
Molybdenum	ppm	<1	0	 
Nickel	ppm	<b>■&lt;1</b>	П0	 
Titanium	ppm	<1	0	 
Silver	ppm	0	0	 
Manganese	ppm	4	0	 
Vanadium	ppm	0	0	 
	le le	-		
VOLVO	IFE			 
ADDITIV	IFZ.			
Calcium	ppm	29	0	 
Magnesium	ppm	6	0	 
Zinc	ppm	8	0	 
Phosphorus	ppm	386	441	 
Barium	ppm	4	9	 
_		_	_	



### WHITAKER CONTRACTING

692 CONVICT CAMP RD

GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER Brother Whitaker@whitaker-contracting.comT: (256)298-3905

## Diagnosis

F:

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: WHIGUN **Unique No:** 10963658 Signed: Wes Davis Report Date: 05 Apr 2024

Contact/Location: BROTHER WHITAKER - WHIGUN

ppm

Boron



# **CONSTRUCTION EQUIPMENT**





