

CONSTRUCTION EQUIPMENT
SWO-070729 EPIROC D60-10 TMG23SED0506 - REAR LEFT FINAL

Sample No: VCP436295 Oil Type: {unknown} Job No: SWO-070729

CVMDIE	INFORMATION			
	INFURMATION			
Sample Number		VCP436295	VCP449242	
Sample Date		01 Apr 2024	27 Dec 2023	
Machine Hours		558	263	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL CONI	NITION			
Visc @ 40°C		= 200	100	
Visc @ 40°C	cSt	206	199	
VOLVO				
CONTAM	INATION			
Water	%	NEG	NEG	
Silicon	ppm	■35	8	
Sodium	ppm	■3	1 0	
Potassium	ppm	4	0	
	ррпп			
VOLVO				
WEAR M	ETALS			
Iron	ppm	113	■31	
Copper	ppm	■ 4	0	
Lead	ppm	10	3	
Tin	ppm	■<1	0	
Aluminum	ppm	6	2	
Chromium	ppm	■3	1	
Molybdenum	ppm	<1	0	
Nickel	ppm	■<1	0	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	4	0	
Vanadium	ppm	0	0	
ADDITIV	FC			
Calcium	ppm	28	0	
Magnesium	ppm	5	0	
Zinc	ppm	9	0	
Phosphorus	ppm	400	412	
Barium	ppm	5	10	



WHITAKER CONTRACTING

692 CONVICT CAMP RD

GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER Brother Whitaker@whitaker-contracting.comT: (256)298-3905

Diagnosis

F:

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: WHIGUN **Unique No:** 10963661 Signed: Wes Davis Report Date: 05 Apr 2024

Contact/Location: BROTHER WHITAKER - WHIGUN

ppm

Boron



CONSTRUCTION EQUIPMENT





