

CONSTRUCTION EQUIPMENT SW0-070729 EPIROC D60-10 TMG23SED0506 - COOLANT

Sample No: VCP436290

Oil Type: **CONVENTIONAL COOLANT**

Report Id: WHIGUN [WUSCAR] 06139104 (Generated: 04/09/2024 15:17:22) Rev: 1

Job No: SWO-070729

SAMPLE IN	FORMATION				
Sample Number	-	VCP436290	VCP447595		
Sample Date		01 Apr 2024	27 Dec 2023		
Machine Hours		558	263		
Sample Status		NORMAL	NORMAL		
COOLANT CONDITION					
рН	Scale 0-14	7.79	7.98		
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	524	676		
Percentage Glycol	%	44.7	45.4		
Freezing Point	°C	□ -21	□ -24		
CONTAMINATION					
Coolant Appearance		normal	normal		
Coolant Color		Pink	Pink		



WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976

Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905

F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: WHIGUN **Unique No:** 10963912 Signed: Jonathan Hester Report Date: 09 Apr 2024



CONSTRUCTION EQUIPMENT





