

CONSTRUCTION EQUIPMENT 5333DR TAYLOR RECYCL VOLVO L60H 622736 - FRONT AXLE

Sample No: VCP367171 Oil Type: VOLVO WB 102

Job No: 5333DR TAYLOR RECYCL

VOLVO	E INFORMATION			
Sample Number		VCP367171	VCP367113	
Sample Number		05 Apr 2024	07 Nov 2022	
Machine Hours		4046	2028	
Oil Hours		1000	2000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
Sample Status		NORWAL	NORIVIAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	47.9	43.5	
VOLVO	MINATION			
_		<u>.</u>		
Water	%	NEG	NEG	
Silicon	ppm	1 4	1 0	
Sodium	ppm	■3	- <1	
Potassium	ppm	■0	3	
VOLVO				
WEAR I	METALS			
ron	ppm	□ 33	□29	
Copper	ppm	■ <1	1 <1	
Lead	ppm	0	0	
Tin	ppm	0	0	
Aluminum	ppm	■<1	1 0	
Chromium	ppm	□ <1	<1	
Molybdenum	ppm	4	1	
Nickel	ppm	0	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	2	1 2	
Vanadium	ppm	<1	0	
	P P			
VOLVO	ure			
ADDITIV	NEZ.			
Calcium	ppm	■3533	■4096	
Magnesium	ppm	■27	1 6	
Zinc	ppm	1398	1609	
Phosphorus	ppm	1097	1255	
Barium	ppm	0	0	
_				

121



HIGHWAY EQUIPMENT & SUPPLY CO

PO BOX 127 DRUMS, PA US 18222 Contact: JUSTIN BLOSS justin@hwyequip.com T: (570)788-1127 F: (570)708-2933

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0022 **Unique No:** 10969508 Signed: Wes Davis Report Date: 11 Apr 2024

ppm

115

Boron



CONSTRUCTION EQUIPMENT





