

Sample No: VCP337513 **Oil Type:** VOLVO WB 102

Job No: 5333DR TAYLOR RECYCL

VOLVO	INFORMATION			
	: INFURMATIUR			
Sample Number		VCP337513	VCP367105	
Sample Date		05 Apr 2024	07 Nov 2022	
Machine Hours		4046	2028	
Oil Hours		1000	2000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
VOLVO	DITION			
OIL CON	DITIUM			
Visc @ 40°C	cSt	47.9	43.5	
VOLVO				
CONTAN	MINATION			
_	_	NEC	NEC	
Water	%	NEG	NEG	
Silicon	ppm	■ 14	10	
Sodium	ppm	■3	1	
Potassium	ppm	■0	3	
VOLVO				
WEAR N	METALS			
Iron	ppm	□38	□ 34	
Copper	ppm	1	1	
Lead	ppm	0	0	
Tin	ppm	0	<1	
Aluminum	ppm	■ <1	0	
Chromium	ppm	■<1	<1	
Molybdenum	ppm	3	1	
Nickel	ppm	0	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese		2	1 2	
Vanadium	ppm	<1	0	
variaululli	ppm	<1	U	
VOLVO				
ADDITIN	ES			
Calcium	ppm	■3443	4126	
Magnesium	ppm	■ 26	1 6	
Zinc	ppm	1363	□ 1635	
Phosphorus	ppm	■1062	1278	
Barium	ppm	■0	0	
Boron	ppm	■117	121	
	PP.11			



HIGHWAY EQUIPMENT & SUPPLY CO

PO BOX 127 DRUMS, PA US 18222 Contact: JUSTIN BLOSS justin@hwyequip.com T: (570)788-1127 F: (570)708-2933

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0022Unique No:10969513Signed:Wes DavisReport Date:11 Apr 2024



CONSTRUCTION EQUIPMENT





