

# **CONSTRUCTION EQUIPMENT**687510 VOLVO A40G 752073 - TRANSMISSION (AUTO)



Sample No: VCP437899

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

**Job No:** 687510

TAMPI	E INFORMATION			
_			VCD 42222	 
Sample Number		VCP437899	VCP432200	 
Sample Date		12 Mar 2024	30 Nov 2023	 
Machine Hours		1131	527	 
Oil Hours		1131	527	 
Oil Changed		Not Changd	Not Changd	 
Sample Status		NORMAL	NORMAL	 
OIL CON	DITION			
Visc @ 40°C	cSt	<b>26.4</b>	<b>28.8</b>	 
VISC @ 40 C	CSI	20.4		 
VOLVO				
CONTAI	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>■</b> 9	<b>1</b> 0	 
Sodium	ppm	<b>4</b>	□0	 
Potassium	ppm	O	2	 
			_	
VOLVO	ACTAL C			
WEAR I	NF I ALS			
Iron	ppm	<b>26</b>	■18	 
Copper	ppm	■21	<b>1</b> 6	 
Lead	ppm	<b>0</b>	<b>0</b>	 
Tin	ppm	■3	<b>1</b>	 
Aluminum	ppm	<b>15</b>	<b>5</b>	 
Chromium	ppm	<b>■</b> 0	<b>-</b> <1	 
Molybdenum	ppm	<b>0</b>	<b>0</b>	 
Nickel	ppm	<b>2</b>	<b>-</b> <1	 
Titanium	ppm	0	0	 
Silver	ppm	■0	<b>0</b>	 
Manganese	ppm	■3	<b>2</b>	 
Vanadium	ppm	<1	0	 
ADDITIV	771			
_	-			
Calcium	ppm	<b>81</b>	<b>1</b> 74	 
Magnesium	ppm	■0	0	 
Zinc	ppm	<b>■</b> 7	<b>0</b>	 
Phosphorus	ppm	<b>218</b>	■250	 
Barium	ppm	<b>-&lt;</b> 1	■3	 
Boron	ppm	■81	■93	 



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619

Contact: PM Services

PMServices@ripaconstruction.com

F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:RIPTAMUnique No:10976344Signed:Don BaldridgeReport Date:15 Apr 2024



## **CONSTRUCTION EQUIPMENT**





