CONSTRUCTION EQUIPMENT 512294 LIBERTY GENIE S125 S12511-3151 - SWING DRIVE



VCP438111

SAMPLE INFORMATION

Sample Number

Water

Silicon

Sodium

ADDITIVES

ppm

ppm

ppm

ppm ppm

ppm

Calcium


Zinc

Barium


Boron

Magnesium

Phosphorus



| Iron | ppm | 🔺 789 | | | | |
|------------|-----|--------------|--|--|--|--|
| Copper | ppm | 22 | | | | |
| Lead | ppm | 15 | | | | |
| Tin | ppm | 1 | | | | |
| Aluminum | ppm | 3 | | | | |
| Chromium | ppm | 5 | | | | |
| Molybdenum | ppm | <1 | | | | |
| Nickel | ppm | | | | | |
| Titanium | ppm | <1 | | | | |
| Silver | ppm | 0 | | | | |
| Manganese | ppm | 9 | | | | |
| Vanadium | ppm | <1 | | | | |





ALTA EQUIPMENT COMPANY

1035 WYLIE DRIVE **BLOOMINGTON, IL** US 61705 Contact: JUSTIN PERRY justin.perry@altg.com T: (309)533-9285 F:

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.Gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

| Depot: | VOLVO5054 | | | |
|--|-------------|--|--|--|
| Unique No: | 10979142 | | | |
| Signed: | Sean Felton | | | |
| Report Date: | 17 Apr 2024 | | | |
| Contact/Location: JUSTIN PERRY - VOLVO5054 | | | | |

57

4

40

3

1202


24

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO5054 [WUSCAR] 06149064 (Generated: 04/17/2024 13:58:26) Rev: 1

Contact/Location: JUSTIN PERRY - VOLVO5054