

CONSTRUCTION EQUIPMENT 2859-1 VOLVO SD75B 241405 - DIESEL ENGINE



Sample No: VCP445929

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 2859-1

| VOLVO | | | | |
|-----------------------|------------|-----------------|--------------|--|
| SAMPLE IN | NFORMATION | | | |
| Sample Number | - | VCP445929 | | |
| Sample Date | | 04 Apr 2024 | | |
| Machine Hours | | 507 | | |
| Oil Hours | | 507 | | |
| Oil Changed | | Changed | | |
| Sample Status | | NORMAL | | |
| | | | | |
| OIT CONDI. | TION | | | |
| | - | = 42.2 | | |
| Visc @ 100°C | cSt | ■ 13.3 | | |
| Base Number (BN) | | ■9.1 | | |
| Oxidation (PA) | % | 53 | | |
| VOLVO | | | | |
| CONTAMIN | NATION | | | |
| Water | % | NEG | | |
| Soot % | % | ■0.2 | | |
| Nitration (PA) | % | 52 | | |
| Sulfation (PA) | % | 48 | | |
| Glycol | % | NEG | | |
| Fuel | % | <1.0 | | |
| Silicon | ppm | 7 | | |
| Sodium | ppm | ■<1 | | |
| Potassium | ppm | 2 | | |
| | | | | |
| WEAR ME | TALC | | | |
| _ | | | <u> </u> | |
| Iron | ppm | 1 5 | | |
| Copper | ppm | 2 | | |
| Lead | ppm | | | |
| Tin | ppm | 1 | | |
| Aluminum | ppm | 4 | | |
| Chromium | ppm | ■<1 | | |
| Molybdenum Nickel | ppm | 54 | | |
| | ppm | - <1 | | |
| Titanium | ppm | <1 | | |
| Silver | ppm | 0 | | |
| Manganese Vanadium | ppm | ■<1 <1 | | |
| vallaululil | ppm | <1 | | |
| ADDITIVES | 7 | | | |
| Calcium | | m1204 | | |
| | ppm | ■ 1204 ■ 854 | | |
| Magnesium | ppm | | | |
| Zinc | ppm | 1150 | | |
| Phosphorus | ppm | ■ 970 | | |
| Barium | ppm | 2 | | |
| Boron | ppm | 11 | | |

MCCLUNG-LOGAN EQUIPMENT CO - BRIDGEVILLE

17941 SUSSEX HIGHWAY BRIDGEVILLE, DE US 19933

Contact: MATT CLARK MCLARK@mcclung-logan.com

T: (302)337-3400 F: (302)337-9083

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO1023Unique No:10979833Signed:Don BaldridgeReport Date:18 Apr 2024



CONSTRUCTION EQUIPMENT





