Sample No: VCP449768

Oil Type: VOLVO WB 102

Job No: 41829 LANDMARK

SAMPLE INFORMAT	TION			
Sample Number	VCP449768	_	_	
	VCP449700		 	
Sample Date	12 Apr 2024		 	
Machine Hours	3829		 	
Oil Hours	0		 	
Oil Changed	Changed		 	
Sample Status	NORMAL		 	



BALFOUR BEATTY INFRASTRUCTURE INC

6701 OLD PLANK RD PARKTON, NC US 28371

Contact: Service Manager

T: F:

OIL COP	NDITION			
40°C	cSt	42.5	 	

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	15					
Sodium	ppm	7					
Potassium	ppm	■0					

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

WEAR I	METALS			
Iron	ppm	14	 	
Copper	ppm	■95	 	
Lead	ppm	■<1	 	
Tin	ppm	■0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	1	 	
Nickel	ppm	2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	■<1	 	
Vanadium	ppm	<1	 	

ADDITIVES							
Calcium	ppm	■3916					
Magnesium	ppm	16					
Zinc	ppm	1612					
Phosphorus	ppm	■1335					
Barium	ppm	0					
Boron	mag	127					

Depot:BALPARNCUnique No:10980781Signed:Don BaldridgeReport Date:18 Apr 2024



CONSTRUCTION EQUIPMENT





