

CONSTRUCTION EQUIPMENT 687658 SENNEBOGEN 840E 2236 - LEFT SWING DRIVE



Sample No: VCP436395

Oil Type: MOBIL MOBILGEAR SHC 220

Job No: 687658

SAMPLE	INFORMATIO	N			
Sample Number		VCP436395	VCP391286		
Sample Date		06 Apr 2024	19 Oct 2022		
Machine Hours		9731	6387		
Oil Hours		2000	2000		
Oil Changed		Changed	Changed		
Sample Status		SEVERE	ABNORMAL		
Sample Status		SEVERE	ADNORIVIAL		
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	222	215		
		_	_		
VOLVO	IINATION				
_	IINATION				
Water	%	▲ 1.73	△ 0.509		
Silicon	ppm	■11	5		
Sodium	ppm	■2	■0		
Potassium	ppm	1	2		
WEAR M	IFTAI C				
		A 000	A 042		
Iron	ppm	▲ 988	812		
Copper	ppm	<u>^</u> 173	122		
Lead	ppm	1	<1		
Tin	ppm	<u>^</u> 24	10		
Aluminum	ppm	3	2		
Chromium	ppm	8	5		
Molybdenum	ppm	2	<1		
Nickel	ppm	2	0		
Titanium	ppm	<1	0		
Silver	ppm	<1	0		
Manganese	ppm	8	6		
Vanadium	ppm	<1	0		
VOLVO					
ADDITIV	ES				
Calcium	ppm	18	5 7		
Magnesium	ppm	3	1		
Zinc	ppm	■ 62	87		
Phosphorus	ppm	295	323		
Barium	ppm	■0	2		
Boron		1 6	21		
שטוטוו	ppm			-3-	



FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE DETROIT, MI US 48207 Contact: KEITH HALL keith.hall@fpt1.com T:

F:

Diagnosis

We advise that you check for the source of water entry. The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Bearing and/or gear wear is indicated. There is a high concentration of water present in the oil. The oil is no longer serviceable due to the presence of contaminants.

Depot: FERDET
Unique No: 10982432
Signed: Sean Felton
Report Date: 22 Apr 2024

Contact/Location: KEITH HALL - FERDET



CONSTRUCTION EQUIPMENT





