

# **CONSTRUCTION EQUIPMENT** VOLVO A40G 352987 - REAR AXLE



#### Sample No: VCP436659

Oil	Type:	V
	i ype.	v

#### VOLVO PREMIUM GEAR OIL 85W-140 GL-5

#### Job No:

	E INFORMATION				
Sample Number		VCP436659	 		
Sample Date		15 Apr 2024	 		RIPA AND ASSOC
Machine Hours		3943	 		10149 FISHER AVE
Oil Hours		0	 		TAMPA, FL
Oil Changed		Changed	 		US 33619
Sample Status		NORMAL	 		Contact: PM Servic
					PMServices@ripac
	DITION				T:
Visc @ 40°C	-	=04.0	 -	<u>.</u>	F:
VISC @ 40°C	cSt	94.9	 		
VOLVO					Diagnosis
CONTA	MINATION				Resample at the r
Water	%	NEG	 		to monitor.All cor
Silicon	ppm	<b>42</b>	 		are normal. There
Sodium	ppm	3	 		any contamination
Potassium	ppm	8	 		condition of the c
					the time in service
WEAD	METALS				
Iron	ppm	609	 		
Copper	ppm	15	 		
Lead	ppm	0	 		
Tin	ppm	0	 		
Aluminum	ppm	■10	 		
Chromium	ppm		 		
Molybdenum Nickel	ppm	<b>1</b> 4			
Titanium	ppm	<b>□</b> 2 <1	 		
Silver	ppm	0	 		
Manganese	ppm ppm	25	 		
Vanadium	ppm	0	 		
Variacium	ppm	U			
VOLVO					
ADDITI	VES				
Calcium	ppm	204	 		
Magnesium	ppm	<b>17</b>	 		
Zinc	ppm	<b>122</b>	 		
Phosphorus	ppm	<b>1841</b>	 		
Barium	ppm	0	 		
Boron	ppm	<b>166</b>	 		



### CIATES

'ENUE ices construction.com

next service interval omponent wear rates e is no indication of on in the oil. The oil is acceptable for ce.


Depot:	RIPTAM	
Unique No:	10990328	
Signed:	Sean Felton	
Report Date:	24 Apr 2024	
Contact/Location: PM Services ? - RIPTAM		

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: RIPTAM [WUSCAR] 06154905 (Generated: 04/24/2024 08:50:35) Rev: 1

Contact/Location: PM Services ? - RIPTAM