

# CONSTRUCTION EQUIPMENT VOLVO A40G 352987 - FRONT AXLE



Sample No: VCP438591

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

VOLVO	INFORMATIO	7		
	INFURMATIUI		 e e e e e e e e e e e e e e e e e e e	
Sample Number		VCP438591	 	
Sample Date		15 Apr 2024	 	
Machine Hours		3943	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>51.5</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm		 	
Sodium	ppm	<b>3</b>	 	
Potassium	ppm	<b>3</b>	 	
	ррпп			
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>■</b> 360	 	
Copper	ppm	<b>1</b> 4	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>4</b>	 	
Molybdenum	ppm	<b>1</b> 3	 	
Nickel	ppm	<b>-&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b> 6	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	<b>114</b>	 	
Magnesium		<b>0</b>	 	
Zinc	ppm	<b>■</b> 51	 	
Phosphorus	ppm	2408	 	
Barium	ppm	<b>2408</b>	 	
	ppm	_	 	
Boron	ppm	<b>151</b>	 	



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T: F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10990349Signed:Jonathan HesterReport Date:24 Apr 2024

Contact/Location: PM Services ? - RIPTAM



## **CONSTRUCTION EQUIPMENT**





