

CONSTRUCTION EQUIPMENT

SWA538928 PALM BEACH VOLVO A40G 353295 - WET DISC BRA

Sample No: VCP444758

Oil Type: VOLVO WET BRAKE TRANSAXLE OIL

Job No: SWA538928 PALM BEACH

TAMPI	E INFORMATIO	И		
				_
Sample Number		VCP444758	 	
Sample Date		18 Apr 2024	 	
Machine Hours		3858	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	43.9	 	
VOLVO				
CONTAI	MINATION			
Water	%	NEG	 	
Silicon	ppm	119	 	
Sodium	ppm	7	 	
Potassium	ppm	2	 	
T O COSSIGNI	PPIII			
VOLVO				
WEAR	METALS			
Iron	ppm	<u>▲</u> 83	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	□ <1	 	
Tin	ppm	-<1	 	
Aluminum	ppm	2	 	
Chromium	ppm	1	 	
Molybdenum	ppm	□ <1	 	
Nickel	ppm	6	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITI	VES			
Calcium		2543	 	
	ppm	2545 1 7	 	
Magnesium Zinc	ppm	1193	 	
	ppm	1193 1348		
Phosphorus Barium	ppm	_	 	
	ppm	0	 	
Boron	ppm	103	 	



PALM BEACH AGGREGATES INC

PO BOX 700, 20125 STATE RD 80 LOXAHATCHEE, FL US 33470

Contact: WILLIAM GONZALEZ wgonzalez@palmbeachag.com T: (561)723-0194

F: (561)798-5380

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The iron level is abnormal. The copper level is abnormal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:PALLOXUnique No:10993505Signed:Don BaldridgeReport Date:25 Apr 2024



CONSTRUCTION EQUIPMENT





