

CONSTRUCTION EQUIPMENT X59414 ELGIN PELICA NP42773 - FRONT RIGHT WHEEL HUB

Sample No: VCP437008

Oil Type: MOBIL SHC 629

Job No: X59414

SAMPLE	INFORMATION			
Sample Number	-	VCP437008	 	
Sample Date		17 Apr 2024	 	
Machine Hours		327	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	NITION			
Visc @ 40°C	cSt	151	 	
VOLVO				
CONTAM	MINATION			
Water	%	NEG	 	
Silicon	ppm	<u>^</u> 25	 	
Sodium	ppm	2	 	
Potassium	ppm	■0	 	
	I. I.			
VOLVO	AFTALC			
WEAR M	NE I ALS			
Iron	ppm	■96	 	
Copper	ppm	■8	 	
Lead	ppm	<u>▲</u> 30	 	
Tin	ppm	1	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■2	 	
Molybdenum	ppm	■ 0	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	■3	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	9 5	 	
Magnesium	ppm	0	 	
Zinc	ppm	0	 	
Phosphorus	ppm	409	 	
Barium	ppm	9	 	
Boron	ppm	■<1	 	



SCOTT EQUIPMENT COMPANY LLC - Saint Rose

PO BOX 997 SAINT ROSE, LA US 70087 Contact: DANA FOSHEE

dfoshee@scottcompanies.com

T: (504)461-0961 F: (504)461-0970

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. Elemental level of silicon (Si) above normal indicating ingress of seal material. The condition of the oil is acceptable for the time in service.

Depot: SCOSAI **Unique No:** 10994857 Signed: Jonathan Hester Report Date: 26 Apr 2024

Contact/Location: DANA FOSHEE - SCOSAI



CONSTRUCTION EQUIPMENT





