

CONSTRUCTION EQUIPMENT VOLVO EC480EL 311198 - REAR RIGHT FINAL DRIVE



Sample No: VCP0007893

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

| VOLVO CAMDIF | INFORMATION | | | | |
|---------------|--------------|---------------|-------------|---------------|-----------------------|
| | INI UNMATION | | | | 1400054000 |
| Sample Number | | VCP0007893 | VCP343009 | VCP310315 | VCP254028 |
| Sample Date | | 24 Apr 2024 | 20 Nov 2021 | 22 Apr 2021 | 10 Jul 2019 |
| Machine Hours | | 0 | 4351 | 3018 | 481 |
| Oil Hours | | 0 | 0 | 0 | 481 |
| Oil Changed | | N/A | Changed | Changed | Changed |
| Sample Status | | NORMAL | ABNORMAL | ABNORMAL | ABNORMAL |
| OIL CON | DITION | | | | |
| Visc @ 40°C | cSt | ■314 | □292 | 210 | 165 |
| VOLVO | | | | | |
| CONTAM | IINATION | | | | |
| Water | % | NEG | NEG | NEG | NEG |
| Silicon | ppm | ■23 | ■408 | 422 | 1 4 |
| Sodium | ppm | 0 | 0 | - <1 | ■8 |
| Potassium | ppm | 1 | 0 | 9 | 1 0 |
| | | | | | |
| WEAR M | IFTAI S | | | | |
| Iron | ppm | □ 29 | <u>2520</u> | <u>^</u> 2466 | □ 256 |
| Copper | ppm | ■ <1 | 6 | 7 | 0 |
| Lead | | 1 <1 | 0 | <1 | 1 <1 |
| Tin | ppm | ■ <1 | <1 | 0 | 0 |
| Aluminum | ppm | 2 | 2 9 | 2 2 | 1 0 |
| Chromium | ppm | 1 | 23 | □ 22 □ 24 | 2 |
| Molybdenum | ppm | 2 | <u>5</u> | 0 | _ |
| Nickel | ppm | ■2 ■<1 | | | 0 |
| Titanium | ppm | ■<1 | ■0 ■2 | □ 2 □ 2 | |
| Silver | ppm | 0 | 0 | 0 | |
| | ppm | ■ <1 | □ 18 | 18 | □ 0 □ 3 |
| Manganese | ppm | <1 | <1 | 0 | 0 |
| Vanadium | ppm | <1 | < | U | U |
| VOLVO | | | | | |
| ADDITIV | ES | | | | |
| Calcium | ppm | ■38 | ■185 | ■80 | 2 0 |
| Magnesium | ppm | 1 3 | 1 9 | □16 | □0 |
| Zinc | ppm | ■23 | ■87 | ■ 97 | ■ 4 |
| Phosphorus | ppm | 1012 | ■889 | □707 | 4 09 |
| Barium | ppm | 2 | 0 | 0 | 0 |
| Boron | ppm | <u></u> 213 | 122 | ■84 | 6 |
| | | | _ | _ | - |



ALTA EQUIPMENT COMPANY 8750 PHILIPS HWY JACKSONVILLE, FL US 32256 Contact: SHAWN NORTHCRAFT shawn.northcraft@altg.com

T: (904)737-6000 F: (904)737-1260

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0092Unique No:11002529Signed:Don BaldridgeReport Date:29 Apr 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





