

# CONSTRUCTION EQUIPMENT VOLVO L70H 624689 - REAR AXLE



Sample No: VCP455459

Oil Type: VOLVO WET BRAKE TRANSAXLE OIL

Job No:

VOLVO SAMPLE	INFORMATION			
	. IIVI OIVIM I IOI		VCD 4040 42	 
Sample Number		VCP455459	VCP401243	 
Sample Date		01 May 2024	23 Oct 2023	 
Machine Hours		3009	2462	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		ABNORMAL	ABNORMAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>46.2</b>	<b>46.3</b>	 
VOLVO	ania Tioni			
LUNIAN	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>■</b> 4	<b>4</b>	 
Sodium	ppm	<b>2</b>	<b>1</b>	 
Potassium	ppm	<b>1</b>	<b>0</b>	 
WEAR N	AFTAI C			
_			<b>-</b> 440	
Iron	ppm	127	110	 
Copper	ppm	<u>^</u> 235	234	 
Lead	ppm	<b>5</b>	<b>-</b> <1	 
Tin	ppm	<u>^</u> 21	<u>^</u> 21	 
Aluminum	ppm	<b></b>	0	 
Chromium	ppm	<b>2</b>	<b>2</b>	 
Molybdenum	ppm	<b></b>	<b>0</b>	 
Nickel	ppm	<b>2</b>	<b>1</b>	 
Titanium	ppm	<1	0	 
Silver	ppm	<1	0	 
Manganese	ppm	■3	<b>2</b>	 
Vanadium	ppm	0	0	 
ADDITIV	/ES			
Calcium	ppm	<b>113</b>	<b>□</b> 109	 
Magnesium	ppm	<b>0</b>	0	 
Zinc	ppm	■395	<b>1</b> 403	 
Phosphorus	ррт	389	354	 
Barium		<b>0</b>	0	 
Boron	ppm	<b>4</b>	<1	 
pototi	ppm	<b>4</b>	<	 



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T:

F: (239)481-3302

### Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. We recommend an early resample to monitor this condition.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:11016376Signed:Jonathan HesterReport Date:08 May 2024

Contact/Location: TODD LARK - VOLVO0090



## **CONSTRUCTION EQUIPMENT**





