

CONSTRUCTION EQUIPMENT RENTAL VOLVO A40G 752153 - DIESEL ENGINE



Sample No: VCP444173

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: RENTAL

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP444173		
Sample Date		29 Feb 2024		
Machine Hours		561		
Oil Hours		0		
Oil Changed		Changed		
Sample Status		ATTENTION		
Sample Status		ATTENTION		
VOLVO				
OIL CONDI	TION			
Visc @ 100°C	cSt	10.7		
Base Number (BN)	mg KOH/g	■ 5.1		
Oxidation (PA)	%	58		
CONTAMIN	NATION			
CONTAMIN	NATION		<u> </u>	
Water	%	NEG		
Soot %	%	■ 0.2		
Nitration (PA)	%	83		
Sulfation (PA)	%	58		
Glycol	%	NEG		
Fuel	%	0.4		
Silicon	ppm	28		
Sodium	ppm	■ 3		
Potassium	ppm	2		
WEAR ME	7147			
_				_
ron	ppm	■17		
Copper	ppm	■239		
_ead 	ppm	■ <1		
Tin	ppm	4		
Aluminum	ppm	4		
Chromium	ppm	■0		
Molybdenum	ppm	■89		
Nickel	ppm	1		
Titanium	ppm	■0		
Silver	ppm	■ 0		
Manganese	ppm	■3		
Vanadium	ppm	0		
ADDITIVE	7			
_		-240 1		
Calcium	ppm	2401		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. Fuel content negligible. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.

Depot:VOLVO0093Unique No:11018420Signed:Don BaldridgeReport Date:13 May 2024

ppm

ppm

ppm

ppm

ppm

24

1192

1044

0

21

Magnesium

Phosphorus

Zinc

Barium

Boron



CONSTRUCTION EQUIPMENT





