

CONSTRUCTION EQUIPMENT

ACTION ENVIRONMENTAL VOLVO EC 140B VCP 428552 (S/N NOT GIVEN) - DIESEL ENGINO

Sample No: VCP428552

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: ACTION ENVIRONMENTAL

VOLVO	IFODMATION.				
SAMPLE II	NFORMATION				
Sample Number	-	VCP428552			
Sample Date		27 Feb 2024			
Machine Hours		14			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
VOLVO	TION				
OIL CONDI	IIUN		<u> </u>		_
Visc @ 100°C	cSt	13.1			
Base Number (BN)	mg KOH/g	10.7			
Oxidation (PA)	%	76			
CONTAMIN	IATION				
_					
Water	%	NEG			
Soot %	%	■0.2			
Nitration (PA)	%	43			
Sulfation (PA)	%	60			
Glycol	%	NEG			
Fuel	%	<1.0			
Silicon	ppm	5			
Sodium	ppm	2			
Potassium	ppm	0			
WEAR ME	ZIAT				
_				<u> </u>	
Iron	ppm	9			
Copper	ppm	4			
Lead	ppm	0			
Tin	ppm	□ <1			
Aluminum	ppm	2			
Chromium	ppm	■<1			
Molybdenum	ppm	42			
Nickel	ppm	0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	1			
Vanadium	ppm	0			
VOLVO					
ADDITIVE:	7				
Calcium		1815			
Magnesium	ppm	520			
Zinc	ppm	1168			
Phosphorus	ppm	1108 1022			
rnosphorus	ppm	1022			

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY

khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0093

 Unique No:
 11018421

 Signed:
 Wes Davis

 Report Date:
 09 May 2024

ppm

ppm

0

Barium

Boron



CONSTRUCTION EQUIPMENT





