

CONSTRUCTION EQUIPMENT RENTAL VOLVO EC550 310250 - HYDRAULIC SYSTEM



Sample No: VCP437042

Oil Type: AW HYDRAULIC OIL ISO 46

Job No: RENTAL

VOLVO				
	NFORMATION			
Sample Number	-	VCP437042	 	
Sample Date		29 Feb 2024	 	
Machine Hours		502	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
Visc @ 40°C	cSt	43.5	 	
Acid Number (AN)	mg KOH/g	■ 0.46	 	
CONTAMIN	NATION			
Water	%	NEG	 	

CONTA	MINATION			
Water	%	NEG	 	
Particles >4µm		124950	 	
Particles >6µm		27468	 	
Particles >14µm		■833	 	
ISO 4406:1999 (c)	24/22/17	 	
Silicon	ppm	■ 3	 	
Sodium	ppm	1	 	
Potassium	ppm	■<1	 	

The state of the s				
WEAR	AFTAI C			
WLAIT	ALL I VES			
Iron	ppm	■ 5	 	
Copper	ppm	16	 	
Lead	ppm	0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	0	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	2	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

ADDITI	IVES			
Calcium	ppm	131	 	
Magnesium	ppm	5	 	
Zinc	ppm	518	 	
Phosphorus	ppm	416	 	
Barium	ppm	■ 0	 	
Boron	ppm	■0	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Depot:VOLVO0093Unique No:11018644Signed:Wes DavisReport Date:09 May 2024



CONSTRUCTION EQUIPMENT





GRAPHS

