

# CONSTRUCTION EQUIPMENT RSO-038028 HITACHI 060320 - RIGHT SWING DRIVE



Sample No: VCP447620

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** RSO-038028

SAMPLE	INFORMATIO	N		
Sample Number	_	VCP447620	 	
Sample Date		10 May 2024	 	
Machine Hours		270	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO	DITION			
OIL CON	NULLIUM			
Visc @ 40°C	cSt	<b>189</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon		NEG ■14	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>6</b>	 	
Potassium	ppm	<b>0</b>	 	
VOLVO				
WEAR M	<b>TETALS</b>			
Iron	ppm	<b>149</b>	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	<b>■</b> 0	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■</b> 4	 	
Vanadium	ppm	<1	 	
ADDITIV	IFS			
_		=14		
Calcium	ppm	<b>14</b>		
Magnesium	ppm	<b>0</b>	 	
Zinc	ppm	<b>□</b> 10	 	
Phosphorus	ppm	<b>■</b> 608	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>■</b> 54	 	



#### SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207 Contact: STEPHANI BRITTON

sbritton@saiia.com;doug.bogart@wearcheck.com

T: (205)943-2268 F: (205)943-2269

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SAIBIRUnique No:11036007Signed:Sean FeltonReport Date:22 May 2024



## **CONSTRUCTION EQUIPMENT**





