

CONSTRUCTION EQUIPMENT VOLVO ECR145EL 314057 - SWING DRIVE



Sample No: VCP449862

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

SAMPLE	INFORMATION				
Sample Number		VCP449862	VCP392693	VCP386065	
Sample Date		10 May 2024	27 Jun 2023	12 Sep 2022	
Machine Hours		5111	4163	2982	
Oil Hours		0	1000	500	
Oil Changed		Changed	Changed	Changed	
		NORMAL	NORMAL	NORMAL	
Sample Status		NUKIVIAL	NORIVIAL	NORIVIAL	
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	■303	□ 194	1 93	
VOLVO					
LUNIAN	MINATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	■ 9	1 1	■9	
Sodium	ppm	■ <1	0	0	
Potassium	ppm	2	1	1	
VOLVO					
WEAR	AETALS				
_	IETAL3				
Iron	ppm	■340	691	531	
Copper	ppm	14	1 9	1 4	
Lead	ppm	0	0	□0	
Tin	ppm	■ 0	0	0	
Aluminum	ppm	■ <1	■3	<1	
Chromium	ppm	■3	5	4	
Molybdenum	ppm	7	2	2	
Nickel	ppm	■0	- <1	0	
Titanium	ppm	<1	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	■ 3	■8	6	
Vanadium	ppm	<1	0	0	
ADDITIV	IFS				
_			-05	-60	
Calcium	ppm	81	8 5	□ 62	
Magnesium 	ppm	25	1 6	1 6	
Zinc	ppm	■90	129	1 09	
Phosphorus	ppm	1073	□ 625	600	
Barium	ppm	■0	0	0	
Boron	ppm	158	5 1	5 4	



RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL

TAMPA, FL US 33619

Contact: PM Services

PMS ervices @rip a construction.com

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:11036044Signed:Wes DavisReport Date:22 May 2024

Contact/Location: PM Services ? - RIPTAM



CONSTRUCTION EQUIPMENT





