### CONSTRUCTION EQUIPMENT SW0-071815 EPIROC D60-10 TMG22SED0210 - COOLANT

 Sample No:
 VCP453748

 Oil Type:
 {unknown}

 Job No:
 SWO-071815

VOLVO

SAMPLE II	NFORMATION			
Sample Number	-	VCP453748	 	
Sample Date		15 May 2024	 	
Machine Hours		1974	 	
Sample Status		NORMAL	 	
COOLANT	CONDITION			
рН	Scale 0-14	6.63	 	
Reserve Alkalinity	Scale 0-20		 	
Nitrites	ppm	NT NT	 	
Percentage Glycol	%	<b>47.7</b>	 	
Freezing Point	°C	-28	 	
CONTAMI	NATION			
Coolant Appearance		normal	 	
Coolant Color		Pink	 	



#### COWIN EQUIPMENT COMPANY

2238 PINSON VALLEY PARKWAY BIRMINGHAM, AL US 35217 Contact: TIM JENKINS tjenkins@cowin.com T: (205)856-4008 F: (205)856-2106

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO8528

 Unique No:
 11036207

 Signed:
 Jonathan Hester

 Report Date:
 24 May 2024

 Contact/Location: TIM
 JENKINS - VOLVO8528

## **CONSTRUCTION EQUIPMENT**



# GRAPHS

#### Iron/Tin/Silver

VOLVO

