CONSTRUCTION EQUIPMENT SW1034679 VOLVO ECR235E 315909 - HYDRAULIC SYSTEM

Sample No:VCP440856Oil Type:AW HYDRAULIC OIL ISO 46Job No:SW1034679

VOLVO

SAMPLE I	NFORMATION				
Sample Number	-	VCP440856			
Sample Date		20 May 2024			
Machine Hours		1074			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		ABNORMAL			
OIL CONDI	TION				
Visc @ 40°C	cSt	41.8			
Acid Number (AN)	mg KOH/g	0.43			
CONTAMI	NATION				
Water	%	NEG			
Silicon	ppm	6			
Sodium	ppm	1			
Potassium	ppm	0			
WEAR ME	TALS				
Iron	ppm	1			
Copper	ppm	3			
Lead	ppm	0			
Tin	ppm				
Aluminum	ppm	0			
Chromium	ppm	□ <1			
Molybdenum	ppm	0			
Nickel	ppm				
Titanium	ppm	0			
Silver	ppm	<1			
Manganese	ppm	0			
Vanadium	ppm	0			
	In la				
ADDITIVES					
Calcium	ppm	94			
Magnesium	ppm	0			
Zinc	ppm	534			
	۲۲				

ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO6174Unique No:11047136Signed:Don BaldridgeReport Date:29 May 2024

398

0 🔲

0

Phosphorus

Barium

Boron

ppm

ppm

ppm


CONSTRUCTION EQUIPMENT




GRAPHS

Ferrous Alloys

VOLVO





Report Id: VOLVO6174 [WUSCAR] 06190384 (Generated: 05/29/2024 16:02:04) Rev: 1

Contact/Location: RANDY PRZEKURAT - VOLVO6174