

CONSTRUCTION EQUIPMENT - WET DISC BRAKE



Sample No: VCP455243
Oil Type: VOLVO WB 102

Job No:

SAMPL	E INFORMATION			
Sample Number	-	VCP455243	VCP395829	
Sample Date		06 Jun 2024	25 Feb 2023	
Machine Hours		4000	2203	
Oil Hours		0	1000	
Oil Changed		Changed	Not Changd	
Sample Status		ABNORMAL	ABNORMAL	
VOLVO	IDITION			
OIL CON	<u>.</u>			_
Visc @ 40°C	cSt	40.6	40.3	
CONTA	MINATION			
_	%	NEG	NEG	
Water				
Silicon	ppm	21	2 4	
Sodium	ppm	10	6	
Potassium	ppm	■ 4	2	
VOLVO				
WEAR I	METALS			
ron	ppm	27	2 1	
Copper	ppm	<u> </u>	<u>^</u> 227	
Lead	ppm	4	- <1	
Tin	ppm	<u> </u>	0	
Aluminum	ppm	1	1 2	
Chromium	ppm	<1	1	
Molybdenum	ppm	<u> </u>	0	
Nickel	ppm	6	7	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	2	2	
Vanadium	ppm	0	0	
VOLVO	VEC			
ADDITI	VEZ.			
Calcium	ppm	■3258	4267	
Magnesium	ppm	11	1 1	
Zinc	ppm	1428	□1706	
Phosphorus	ppm	1232	□1389	
Barium	ppm	0	□0	
Boron	ppm	116	128	



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

F: (239)481-3302

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:11074365Signed:Don BaldridgeReport Date:13 Jun 2024



CONSTRUCTION EQUIPMENT





