

# CONSTRUCTION EQUIPMENT SWO-072572 APAC VOLVO L150G 23109 - REAR AXLE



Sample No: VCP439787
Oil Type: VOLVO AT 102

Job No: SWO-072572 APAC

SAMPLE	E INFORMATION			
Sample Number		VCP439787	 	
Sample Date		04 Jun 2024	 	
Machine Hours		4217	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>51.2</b>	 	
VISC @ 40 C	CSI	<b>51.2</b>	 	
VOLVO				
CONTAI	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>17</b>	 	
Sodium	ppm	<b>■</b> 8	 	
Potassium	ppm	<b>4</b>	 	
VOLVO	AFTALC			
WEAR I	METAL2			
Iron	ppm	<b>50</b>	 	
Copper	ppm	<b>4</b>	 	
Lead	ppm	<b>4</b>	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	<b>■</b> 3	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b>	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	VES			
Calcium	ppm	■3144	 	
Magnesium	ppm	<b>33</b>	 	
Zinc	ppm	■1309	 	
Phosphorus	ppm	<b>1082</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>119</b>	 	
		_		



#### **COWIN EQUIPMENT COMPANY**

2238 PINSON VALLEY PARKWAY BIRMINGHAM, AL US 35217

Contact: BRANTLY CLAY bclay@cowin.com

T:

F: (205)856-2106

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8528Unique No:11074386Signed:Don BaldridgeReport Date:13 Jun 2024



## **CONSTRUCTION EQUIPMENT**





