

## CONSTRUCTION EQUIPMENT 136502 VOLVO A40G 752154 - FRONT AXLE



Sample No: VCP450624
Oil Type: {unknown}
Job No: 136502

VOLVO		N		
	INFORMATIO	N .		
Sample Number		VCP450624	VCP442500	 
Sample Date		07 Jun 2024	03 Apr 2024	 
Machine Hours		880	530	 
Oil Hours		0	0	 
Oil Changed		Changed	Not Changd	 
Sample Status		NORMAL	NORMAL	 
OIL CON	DITION			
Visc @ 40°C	cSt	<b>52.5</b>	<b>52.6</b>	 
VOLVO	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>4</b>	<b>4</b>	 
Sodium	ppm	<b>1</b>	<b>3</b>	 
Potassium	ppm	<b>■</b> 4	<b>2</b>	 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>250</b>	□209	 
Copper	ppm	<u> </u>	<1	 
Lead	ppm	<b>0</b>	0	 
Tin	ppm	<1	0	 
Aluminum	ppm	<u> </u>	П0	 
Chromium	ppm	<b>4</b>	3	 
Molybdenum	ppm	9	9	 
Nickel	ppm	<b>■&lt;1</b>	0	 
Titanium	ppm	<1	0	 
Silver	ppm	0	0	 
Manganese	ppm	14	14	 
Vanadium	ppm	<1	0	 
	le le			
ADDITIV	/ES			
Calcium	ppm	113	155	 
Magnesium	ppm	1	<1	 
Zinc		52	57	 
Phosphorus	ppm	2473	2402	 
Barium	ppm	0	<1	 
	ppm			 
Boron	ppm	339	272	 



LATTIMORE MATERIALS/HOLCIM - ROSSER - LAFARGE
14242 S SH-34
SCURRY, TX
US 75158
Contact: WALLACE WARREN
wallace.warren@lafargeholcim.com
T:
F:

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LATSCUUnique No:11075566Signed:Wes DavisReport Date:14 Jun 2024



## **CONSTRUCTION EQUIPMENT**





