

CONSTRUCTION EQUIPMENT VOLVO ECR145 316780 - SWING DRIVE



Sample No: VCP443017

Oil Type: GEAR OIL SAE 85W140

Job No:

VOLVO	INFORMATION			
	INFURMATIUM		 e e e e e e e e e e e e e e e e e e e	-
Sample Number		VCP443017	 	
Sample Date		11 Jun 2024	 	
Machine Hours		516	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	173	 	
VOLVO				
CONTAN	MOITAMIN			
Water	%	NEG	 	
Silicon	ppm	18	 	
Sodium	ppm	■<1	 	
Potassium	ppm	1	 	
VOLVO	AFTALC			
WEAR N	NE I ALS			
Iron	ppm	59	 	
Copper	ppm	■28	 	
Lead	ppm	■<1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	1	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	■<1	 	
Nickel	ppm	■<1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
	•			
ADDITIV	IES			
Calcium	ppm	71	 	
Magnesium	ppm	1	 	
Zinc	ppm	■ 50	 	
Phosphorus	ppm	■313	 	
Barium	ppm	2	 	
Boron	ppm	3	 	
DOTOIT	PPIII			



RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T:

Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:11083348Signed:Sean FeltonReport Date:18 Jun 2024



CONSTRUCTION EQUIPMENT





