



CONSTRUCTION EQUIPMENT

PRINCE VOLVO L90H 627129 - TRANSMISSION (AUTO)



Sample No: VCP444776
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: PRINCE



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP444776	---	---	---
Sample Date	09 Apr 2024	---	---	---
Machine Hours	908	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	ABNORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 28.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 3	---	---	---



WEAR METALS

Iron	ppm	▲ 176	---	---	---
Copper	ppm	█ 9	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 3	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 9	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	71	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 36	---	---	---
Phosphorus	ppm	█ 184	---	---	---
Barium	ppm	█ 1	---	---	---
Boron	ppm	█ 74	---	---	---

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The iron level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 11083475
Signed: Angela Borella
Report Date: 17 Jun 2024



CONSTRUCTION EQUIPMENT



GRAPHS

