

# CONSTRUCTION EQUIPMENT RSO-038391 HITACHI 060320 - LEFT SWING DRIVE



Sample No: VCP443966

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** RSO-038391

SAMPLE	INFORMATION			
Sample Number		VCP443966	VCP447623	 
Sample Date		20 Jun 2024	10 May 2024	 
Machine Hours		530	270	 
Oil Hours		0	0	 
Oil Changed		Not Changd	Changed	 
Sample Status		NORMAL	NORMAL	 
Sample Status		NORIVIAL	NORIVIAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>202</b>	<b>1</b> 91	 
		_	_	
VOLVO	AINATION			 
LUNIAN	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>16</b>	<b>1</b> 0	 
Sodium	ppm	<b>2</b>	<b>2</b>	 
Potassium	ppm	<b>2</b>	<b>3</b>	 
WEAR	AFTAI S			
_		= 100		
Iron	ppm	<b>■</b> 103	<b>6</b> 2	 
Copper	ppm	<b>2</b>	<b>-</b> <1	 
Lead	ppm	<b>0</b>	0	 
Tin	ppm	<b>■</b> 0	0	 
Aluminum	ppm	<b>0</b>	0	 
Chromium	ppm	<b>2</b>	1	 
Molybdenum	ppm	<b>   &lt;1</b>	0	 
Nickel	ppm	<b>0</b>	0	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	<b>3</b>	<b>2</b>	 
Vanadium	ppm	0	<1	 
VOLVO				
ADDITIV	/ES			
Calcium	ppm	■36	<b>-</b> <1	 
Magnesium	ppm	<b>1</b> 5	0	 
Zinc	ppm	<b>1</b> 49	■112	 
Phosphorus	ppm	<b>499</b>	524	 
Barium	ppm	2	0	 
Boron	ppm	■39	<b>3</b> 5	 
231011	PPIII			



#### SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207

Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com

T: (205)943-2268 F: (205)943-2269

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SAIBIRUnique No:11099799Signed:Angela BorellaReport Date:28 Jun 2024



## **CONSTRUCTION EQUIPMENT**





