

CONSTRUCTION EQUIPMENT VOLVO A45G 352344 - COOLANT



Sample No: VCP0008172
Oil Type: {unknown}

Job No:

| SAMPLE IN | NFORMATION | | | | |
|--------------------|------------|-------------|--|--|--|
| Sample Number | • | VCP0008172 | | | |
| Sample Date | | 19 Jun 2024 | | | |
| Machine Hours | | 0 | | | |
| Sample Status | | NORMAL | | | |
| | | | | | |
| COOLANT CONDITION | | | | | |
| pН | Scale 0-14 | ■ 8.29 | | | |
| Reserve Alkalinity | Scale 0-20 | | | | |
| Nitrites | ppm | ■ NT | | | |
| Percentage Glycol | % | 44.1 | | | |
| Freezing Point | °C | -21 | | | |
| | | | | | |
| CONTAMINATION | | | | | |
| Coolant Appearance | | normal | | | |
| Coolant Color | | Yllow | | | |



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

1:

F: (904)737-1260

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:VOLVO0092Unique No:11101012Signed:Jonathan HesterReport Date:01 Jul 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





GRAPHS

