CONSTRUCTION EQUIPMENT SWA590217-20 VOLVO A30G 752316 - FRONT AXLE



Sample No:	VCP435823		
Oil Type:	{unknown}		
Job No:	SWA590217-20		

VOLVO

SAMPLE INFORMATION

	VCP435823 20 Jun 2024 3960 0 N/A	VCP379709 29 Nov 2022 2557 0		
	3960 0	2557		
	0			
		0		
	N/A			
	,	Changed		
	ABNORMAL	ABNORMAL		
N				
	95.6	977		
TION				
%	NEG	▲ 0.388		
opm	20	30		
opm	0	0		
opm	7	0		
LS				
opm	877	514		
opm	A 303	42		
pm	0	0		
opm	1 7	0		
pm	3	6		
opm	16	□10		
pm	13	14		
opm	7	 <1		
pm	<1	<1		
pm	0	0		
pm	31	23		
opm	0	0		
	DN St St TION % ppm ppm ppm ppm ppm ppm ppm ppm ppm p	DN aSt 95.6 TION 6 NEG oppm 20 oppm 0 oppm 7 LS 877 oppm 303 oppm 0 oppm 17 oppm 16 oppm 7 oppm 7 oppm 33 oppm 16 oppm 7 oppm 3 oppm 3	N 95.6 97.7 TION 0 97.7 6 NEG 0.388 oppm 20 30 oppm 0 0 oppm 7 0 LS 0 0 oppm 303 42 oppm 17 0 oppm 16 10 oppm 7 <1	N 95.6 97.7 TION 6 NEG 0.388 60 0 0 60 0 0 70 0 00 0 00 0 00 0 00 0 00 0 00 0 00 0 >>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>

ALTA EQUIPMENT COMPANY

5210 REESE ROAD DAVIE, FL US 33314 Contact: N. FACEY nfacey@altaequipfl.com T: (954)581-4744 F: (954)583-0318

Diagnosis

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

ADDITIVES							
Calcium	ppm	1094	656				
Magnesium	ppm	5	10				
Zinc	ppm	428	313				
Phosphorus	ppm	1718	1336				
Barium	ppm	5	7				
Boron	ppm	309	155				

 Depot:
 VOLVO0095

 Unique No:
 11110078

 Signed:
 Don Baldridge

 Report Date:
 05 Jul 2024


 Contact/Location: N. FACEY - VOLVO0095

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



D---- 2