

CONSTRUCTION EQUIPMENT VOLVO A45G 342727 - COOLANT



Sample No:VCP0008465Oil Type:{unknown}

Job No:

IT UKMA I IUN				_
	VCP0008465			
	27 Jun 2024			
	3922			
	ABNORMAL			
Scale 0-14	7.76			
Scale 0-20				
ppm	NT			
%	A 33.7			
°C	0			
IATION				
ATION	normal			
	Scale 0-20 ppm %	VCP0008465 27 Jun 2024 3922 ABNORMAL CONDITION Scale 0-14 7.76 Scale 0-20 ppm NT % ▲ 33.7	VCP0008465 27 Jun 2024 3922 ABNORMAL CONDITION Scale 0-14 7.76 ppm NT % 4 33.7	VCP0008465 27 Jun 2024 3922 ABNORMAL CONDITION Scale 0-14 7.76 Scale 0-20 Ppm NT % ▲ 33.7



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256 Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com T: F: (904)737-1260

Diagnosis

We recommend that you perform a partial drain and top off with straight antifreeze to increase level of glycol. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is lower than acceptable. The pH level of this fluid is within the acceptable limits.

Depot:	VOLVO0092			
Unique No:	11111534			
Signed:	Jonathan Hester			
Report Date:	08 Jul 2024			
Submitted By: TECHNICIAN ACCOUNT				
	Page 1 of 2			


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Report Id: VOLVO0092 [WUSCAR] 06228041 (Generated: 07/09/2024 12:20:14) Rev: 1

Submitted By: TECHNICIAN ACCOUNT