

CONSTRUCTION EQUIPMENT 715570 VOLVO ECR145EL 315939 - REAR RIGHT FINAL DRIVE

AL DRIVE

Sample No: VCP451475

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 715570

VOLVO CAMDIE	INFORMATION				
	INFURMATION				
Sample Number		VCP451475	VCP392712	VCP367204	
Sample Date		14 Jun 2024	28 Apr 2023	12 Sep 2022	
Machine Hours		2070	1009	495	
Oil Hours		1000	500	495	
Oil Changed		Changed	Changed	Changed	
Sample Status		ABNORMAL	ABNORMAL	ABNORMAL	
OIL CON	DITION				
Visc @ 40°C	cSt	275	E 225	m 120	
VISC @ 40 C	CSL	2/3	□235	1 39	
VOLVO					
CONTAM	IINATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	■8	9	1 1	
Sodium	ppm	2	- <1	1 2	
Potassium	ppm	2	1	1	
	le le				
VOLVO					
WEAR M	IETALS				
Iron	ppm	150	■209	257	
Copper	ppm	■<1	0	- <1	
Lead	ppm	0	0	0	
Tin	ppm	<u> </u>	1 8	<u>^</u> 21	
Aluminum	ppm	2	< 1	0	
Chromium	ppm	2	4	5	
Molybdenum	ppm	5	6	- <1	
Nickel	ppm	■<1	1	0	
Titanium	ppm	<1	<1	0	
Silver	ppm	0	0	0	
Manganese	ppm	2	4	6	
Vanadium	ppm	0	0	0	
VOLVO	IEC				
ADDITIV	D				
Calcium	ppm	□ 74	144	■29	
Magnesium	ppm	■27	4 3	 <1	
Zinc	ppm	■81	□121	■ 25	
Phosphorus	ppm	■952	■816	243	
Barium	ppm	0	0	0	
Boron	ppm	141	134		



RIPA AND ASSOCIATES 10149 FISHER AVENUE TAMPA, FL US 33619

Contact: PM Services

PMS ervices @ripacon struction.com

F:

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. The tin level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:11127025Signed:Sean FeltonReport Date:18 Jul 2024

Contact/Location: PM Services ? - RIPTAM



CONSTRUCTION EQUIPMENT





