



ZF HURTH 132520321800 - STARBOARD GEAR UNIT

Sample No: VPA044259
Oil Type: NOT GIVEN

SAMPLE INFORMA	TION			
SAMPLE INFURMA	ITIUN			
Sample Number		VPA044259	 	
Sample Date		22 Nov 2022	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 40°C	cSt	□ 93.7	 	
VISC @ 40 C	CSI		 	
CONTAMINATION				
Silicon	ppm	12	 	
Sodium	ppm	2	 	
Potassium	ppm	0	 	
	PP			
WEAR METALS				
PQ		■ 0	 	
Iron	ppm	12	 	
Copper	ppm	11	 	
Lead	ppm	■<1	 	
Tin	ppm	■<1	 	
Aluminum	ppm	2	 	
Chromium	ppm	0	 	
Molybdenum	ppm	95	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	2235	 	
Magnesium	ppm	22	 	
Zinc	ppm	966	 	
Phosphorus	ppm	951	 	
Barium	ppm	0	 	
Boron	ppm	11	 	
	P P	-		

TORONTO YACHT SERVICES

475 UNWIN AVE TORONTO, ON CA M4M 3M2 Contact: Jon info@torontoyachtservices.com T: (416)886-9992 F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:TOR101TORUnique No:5489460Signed:Kevin MarsonReport Date:24 Nov 2022





