

OIL ANALYSIS REPORT

VOLVO PENTA

4 FROGS 6732-54461 - GENSET

Sample No: VPA044664

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMATION

Sample Number	VPA044664	VPA032084	---	---
Sample Date	04 Nov 2022	02 Oct 2021	---	---
Machine Hours	0	0	---	---
Oil Hours	0	0	---	---
Oil Changed	N/A	Not Changd	---	---
Sample Status	NORMAL	NORMAL	---	---

OIL CONDITION

Visc @ 100°C	cSt	█ 13.8	█ 14.3	---	---
Base Number (BN)	mg KOH/g	█ 8.6	---	---	---
Oxidation (PA)	%	65	67	---	---

CONTAMINATION

Soot %	%	█ 0.1	█ 0.1	---	---
Nitration (PA)	%	53	53	---	---
Sulfation (PA)	%	55	57	---	---
Glycol	%	NEG	NEG	---	---
Fuel	%	<1.0	<1.0	---	---
Silicon	ppm	█ 4	█ 3	---	---
Sodium	ppm	█ 2	█ 1	---	---
Potassium	ppm	█ 8	█ 8	---	---

WEAR METALS

Iron	ppm	█ 3	█ 3	---	---
Copper	ppm	█ 1	█ 4	---	---
Lead	ppm	█ 2	█ <1	---	---
Tin	ppm	█ <1	█ <1	---	---
Aluminum	ppm	█ <1	█ 1	---	---
Chromium	ppm	█ <1	█ <1	---	---
Molybdenum	ppm	█ <1	█ 2	---	---
Nickel	ppm	█ <1	█ <1	---	---
Titanium	ppm	0	<1	---	---
Silver	ppm	█ 0	1	---	---
Manganese	ppm	█ <1	█ <1	---	---
Vanadium	ppm	<1	<1	---	---

ADDITIVES

Calcium	ppm	█ 2266	█ 2271	---	---
Magnesium	ppm	█ 16	█ 17	---	---
Zinc	ppm	█ 1254	█ 1276	---	---
Phosphorus	ppm	█ 1022	█ 1007	---	---
Barium	ppm	█ 0	█ 0	---	---
Boron	ppm	█ 197	█ 216	---	---

The Talaria Company

202 Banks St., One Little Harbor Landing
OXFORD, MD
US 21654
Contact: TRACY PELLERIN
tpellerin@hinckleyyachts.com
T: (410)770-4899
F: x:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP592286
Unique No: 10319194
Signed: Sean Felton
Report Date: 01 Feb 2023

OIL ANALYSIS REPORT

VOLVO PENTA

GRAPHS

