## **OIL ANALYSIS REPORT**

#### SUMNER ROAD 2915 5GA656 - INBOARD - CENTER GEARBOX

Sample No: VPA056964

**Oil Type:** SHELL ROTELLA T 30

#### SAMPLE INFORMATION VPA056964 Sample Number The Talaria Company 02 Feb 2023 Sample Date Machine Hours 896 **Oil Hours** 34 US 21654 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** F: x: Visc @ 40°C cSt 92.1 CONTAMINATION % Water NEG Silicon ppm 4 Sodium 0 🔲 ppm Potassium ppm 2 WEAR METALS PO 12 5 Iron ppm Copper 103 ppm Lead 70 ppm Tin 0 🔲 ppm 1 Aluminum ppm Chromium ppm 0 Molybdenum 110 ppm 0 🔲 Nickel ppm Titanium 0 ppm Silver 0 ppm 0 Manganese ppm Vanadium 0 ppm **ADDITIVES** 2418 Calcium ppm Magnesium ppm 48 Zinc ppm 1028 Phosphorus ppm 964 Barium 0 🔲 ppm Boron ppm 0



202 Banks St., One Little Harbor Landing OXFORD, MD Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal for OEM. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot: VP592286 Unique No: 10338684 Signed: Doug Bogart **Report Date:** 19 Feb 2023

Contact/Location: TRACY PELLERIN - VP592286

# **OIL ANALYSIS REPORT**



### GRAPHS



Contact/Location: TRACY PELLERIN - VP592286