



PRELLWITZ WESTERBEKE 2090720H - GENSET

Sample No: VPA035708

Oil Type: SHELL ROTELLA T 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA035708	VPA035707	
Sample Date		23 May 2023	07 May 2023	
Machine Hours		0	496	
Oil Hours		1	1	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	SEVERE	
OIL CONDITION				
Visc @ 100°C	cSt	14.2		
Base Number (BN)		9.7	13.0	
Oxidation (PA)	%	64	60	
	70	04		
CONTAMINATION				
Water	%		1.51	
Soot %	%	■0.1	■ 0.1	
Nitration (PA)	%	54	62	
Sulfation (PA)	%	54	38	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	■0.4	
Silicon	ppm	■8	7	
Sodium	ppm	■ 3	0	
Potassium	ppm	2	4	
WEAR METALS				
Iron	ppm	<u>^</u> 47	2 3	
Copper	ppm	2	- <1	
Lead	ppm	■ 0	□0	
Tin	ppm	■<1	- <1	
Aluminum	ppm	6	5	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	41	40	
Nickel	ppm	■ 0	0	
Titanium	ppm	0	<1	
Silver	ppm	■ 0	0	
Manganese	ppm	■<1	<1	
Vanadium	ppm	0	0	
ADDITIVES				
Calcium	ppm	1547	1686	
Magnesium	ppm	465	498	
Zinc	ppm	1200	1258	
Phosphorus	ppm	1000	1027	
Barium	ppm	□0	0	
Boron	ppm	72	65	
	1-1			

Walstrom Marine

501 Bay Street HARBOR SPRINGS, MI US 49740 Contact: RICK HEINY rheiny@walstrom.com T: F:

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Cylinder, crank, or cam shaft wear is indicated. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP154879Unique No:10485202Signed:Sean FeltonReport Date:25 May 2023

OIL ANALYSIS REPORT



