



MARINE MAX PACKER FAN 14093 MORINENN LIGHTS 8442-49900 - GENSET

Sample No: VPA056616
Oil Type: NOT GIVEN

SAMPLE INFORMAT	TION			
Sample Number		VPA056616	 	
Sample Date		20 Jun 2023	 	
Machine Hours		15620	 	
Oil Hours		173	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	13.9	 	
Base Number (BN)	mg KOH/g	9.6	 	
Oxidation (PA)	%	73	 	
Oxidation (PA)	70	/3	 	
CONTAMINATION				
Soot %	%	0.2	 	
Nitration (PA)	%	63	 	
Sulfation (PA)	%	58	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■8	 	
Sodium	ppm	3	 	
Potassium	ppm	0	 	
WEAR METALS				
Iron	ppm	2	 	
Copper	ppm	O	 	
Lead	ppm	■0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■0	 	
Chromium	ppm	0	 	
Molybdenum	ppm	42	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese		0	 	
Vanadium	ppm	0	 	
ADDITIVES	ррш			_
	10.10.100	1142		
Calcium	ppm	1142	 	
Magnesium	ppm	742	 	
Zinc	ppm	816	 	
Phosphorus	ppm	637	 	
Barium	ppm	0	 	
Boron	ppm	39	 	

PARTS & POWER

PO BOX 1305498, PMB1000-00 ST THOMAS, VI US 00803 Contact: KARIM PERSAUD info@partsandpower.com T: (284)494-2830 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP981217Unique No:10540008Signed:Angela BorellaReport Date:06 Jul 2023

OIL ANALYSIS REPORT



